

40kg Digital Scales Calibration Instructions



KL20121

KegLand Distribution PTY LTD

www.kegland.com.au



Step 1. Turn on the scales and allow the values on the screen to stabilise.

Step 2. Use the numeric keypad to input the password **3658** and then quickly press **TARE**. CAL will show on the WEIGHT(kg) display indicating you have successfully entered the calibration mode.

Step 3. Input **1** using the numeric keypad and press **TARE**. The TOTAL PRICE display should show “-----”

Step 4. Place a known weight of at least half of the full capacity (more than 20kg for the 40kg digital scales) onto the scales. Then press **TARE**

Step 5. Input the value of the known weight used in grams (for example if your calibration weight is 20kg then input 20000). Then press **TARE**

Step 6. Input the maximum capacity of the scales in grams. For these Scales input 40000 and then press **TARE**

Step 7. Input **3** using the numeric keypad and press **TARE**.

Step 8. Input the desired value of division **5** using the numeric keypad then press **TARE**.

If the scale measures the correct weight, then the calibration has been successful.

Step 9. Remove the weight and switch the scales Off and On again.